

## EUSAAR CPC and D/SMPS Calibration Workshop 2006 Time Schedule

	Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday	Monday	Tuesday	Wednesday	
Time	12.11.06	13.11.06	14.11.06	15.11.06	16.11.06	17.11.06	18.11.06	19.11.06	20.11.06	21.11.06	22.11.06	
08:00	Traveling  (no lunch at IFT)	Briefing/ Lecture	Briefing/ Lecture	Briefing/ Lecture	Briefing/ Lecture	Briefing/ Lecture	Briefing	We will work on one day of the weekend, which one will be decided during the workshop	Briefing	Briefing	Departure & Traveling  (Public Holiday in Saxony!)	
09:00		CPC Calibration I	CPC Calibration I	CPC Calibration I  Discussion of Results	Spectrometer Audit	D/SMPS calibration & CPC calibration II	D/SMPS calibration & CPC calibration II		D/SMPS calibration & CPC calibration II	D/SMPS calibration & CPC calibration II		
10:00		Lunch (two groups)	Lunch (two groups)	Lunch (two groups)	Lunch (two groups)	Lunch (two groups)	Lunch (two groups)		Lunch (two groups)	Lunch (two groups)		Lunch (two groups)
11:00		CPC Calibration I	CPC Calibration I	Spectrometer Setup	Spectrometer Audit	D/SMPS calibration & CPC calibration II	D/SMPS calibration & CPC calibration II		D/SMPS calibration & CPC calibration II	D/SMPS calibration & CPC calibration II		Workshop Reflection, Future Planning, & Homework
12:00	Coffee Break & Info	Coffee Break & Info	Coffee Break & Info	Coffee Break & Info	Coffee Break & Info	Coffee Break & Info	Coffee Break & Info		Coffee Break & Info	Instrument Disassembly		
13:00	Welcome & Kick-off Meeting	CPC Calibration I	CPC Calibration I	Spectrometer Test	D/SMPS calibration & CPC calibration II	D/SMPS calibration & CPC calibration II	D/SMPS calibration & CPC calibration II		D/SMPS calibration & CPC calibration II			Packing
14:00		Unpacking	CPC Calibration I	CPC Calibration I	Spectrometer Test	D/SMPS calibration & CPC calibration II	D/SMPS calibration & CPC calibration II		D/SMPS calibration & CPC calibration II	D/SMPS calibration & CPC calibration II		End of workshop
15:00	Instrument Assembly	CPC Calibration I	CPC Calibration I	Workshop Dinner						Departure & Traveling		
16:00		Coffee, Tea, & Cakes	CPC Calibration I	CPC Calibration I								
17:00												
18:00												
19:00												
20:00												
21:00							Saturday Night Fever					